

1



A close-up photograph of a metal beam, likely a steel I-beam, showing a vertical crack and a horizontal crack. The vertical crack is located on the upper flange, and the horizontal crack is located on the web. The beam is painted a light color, and the cracks are dark and clearly visible.